

ATTACHMENT F - 11/06/2023 Photos



Photo 1: Upstream view looking east-northeast from Maple Avenue.



Photo 2: View of upstream culvert inlet, looking west-southwest from the rock wall upstream of Maple Avenue.



Photo 3: Downstream view looking west-southwest from Maple Avenue.



Photo 4: View of downstream culvert outlet, perched $\pm 5'$, looking east-northeast.



Photo 5: View looking north along Maple Avenue toward the crossing site.



Photo 6: View looking south along Maple Avenue toward the crossing site. The existing culvert is approximately six feet beyond the utility pole on the right side of the photo.